


PFA變徑直接頭



尺寸	孔徑	A	B	C
3/8"x1/4"	3.3	65.3	30.7	27.7
1/2"x1/4"	3.3	67.8	33.3	27.7
1/2"x3/8"	6.4	70.9	33.3	30.7
3/4"x1/4"	3.3	72.4	37.6	27.7
3/4"x3/8"	6.4	75.9	37.6	30.7
3/4"x1/2"	9.7	78.0	37.6	33.7
1"x1/2"	9.7	84.6	43.9	33.5
1"x3/4"	16	88.6	43.7	37.6
1 1/4"x1/2"	9.7	85.1	44.5	33.3
1 1/4"x1"	22.4	90.1	44.5	37.6
1 1/2"x3/4"	16	89.4	44.5	37.6